

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/02/2012	3. Time Prepared 1745
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 09/27/12 – 0700, 10/04/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Larry Rader		Situation Unit Leader	Chicago, Illinois
8. Activity Log			
Time	Major Events		
1000	Boat safety briefing at C0.4 boat launch. Launch. <ul style="list-style-type: none"> Sheen and tar globules observed along Ceresco Dam control point. 		
1330	Helicopter safety briefing, take off. <ul style="list-style-type: none"> Source Area, restoration activities appear complete. Source area, crews observed inspecting monitoring wells south of the pipeline. Frac-Tank City, no activity observed. Confluence, no sheen or activity observed. Sheen sweeper boat observed in river channel near MP 5.00. Sheen and tar globules observed along Ceresco Dam control point. During afternoon overflight, no sheen observed at Ceresco Dam. MP10.75 sediment trap, no sheen observed. RI crews observed along LDB near MP 14.5 upstream from Mill Ponds. MP15.5 Mill Ponds, no sheen observed during overflight. Enbridge safety boat observed at Fort Custer boat launch. MP33.0A, observed boat crew near sediment trap. Morrow Lake Delta, poling crew observed along boom configuration B. Morrow Lake Delta, poling crew observed along boom configuration B. Pontoon boat crew observed hauling debris bags to the E4 boat launch. Main channel of Morrow Lake, no sheen observed. No sheen observed in north or south coves of Morrow Lake during overflight. Morrow Lake Dam, flow observed through both spillways. 		
	Additional observations: None		
1530	Return to ICP.		
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START			